

Technical drawing of a stepped shaft. The shaft has three steps. The first step has a diameter of 3 and a length of 1. The second step has a diameter of 2 and a length of 1. The third step has a diameter of 10 and a length of 2. The drawing shows the shaft in perspective, with the steps clearly defined by changes in diameter and length.

Technical drawing of a stepped shaft. The shaft has three steps. The first step has a diameter of 3 and a length of 1. The second step has a diameter of 2 and a length of 1. The third step has a diameter of 10 and a length of 2. The drawing shows the shaft in perspective, with the steps clearly defined by changes in diameter and length.